


MEASURING

Measure the opening width and height in several places (see below) and record the smallest width and height measurement.



1. Record the **smallest** of each measurement, height and width in the “record” box above
2. Transfer these measurements to the order form drop downs under opening height and width

Please be careful to measure to 1/16 of an inch increments

Note: The measuring is different (slightly smaller) for “recess” mount versus surface mount applications. **See above 1-A and 1-B**